

Please take note of the orientation of the EPROM chips. Failure to insert the chip in the proper direction may result in damage to the chips.

